



H10
Drawing 41803
S. Zimmerman

Sheet 1 of 15




FIGURE 2




FIGURE 3








FIGURE 1





Sheet 3 of 15








FIGURE 11




FIGURE 12





FIGURE-13






FIGURE 16




FIGURE 14




FIGURE 15




FIGURE 17




FIGURE 18




FIGURE 19




FIGURE 21



FIGURE 20





FIGURE 22



Sheet 8 of 15




FIGURE 23





FIGURE 25






FIGURE 26

FIGURE 27




FIGURE 28



FIGURE 30




FIGURE 31












FIGURE 29










FIGURE 38





FIGURE 39




FIGURE 43




FIGURE 44




FIGURE 41

FIGURE 42

